

51.	V-355B	1/4"(DN8) ~ 4" (DN100)	Butt Weld	3 Pieces	2000/1500/100 0PSI/PN140/P N100/PN63	Full Bore
52.	V-355S	1/4"(DN8) ~ 4" (DN100)	Socket Weld	3 Pieces	2000/1500/100 0PSI/PN140/P N100/PN63	Full Bore
53.	V-355T	1/4"(DN8) ~ 4" (DN100)	Threaded	3 Pieces	2000/1500/100 0PSI/PN140/P N100/PN63	Full Bore
54.	V-103P	1/4"(DN8) ~ 2" (DN50)	Threaded	1 piece	800 PSI /PN40	Reduced Bore
55.	NV-0060	1/8"(DN6) ~ 2" (DN50)	Threaded	Needle Valve	6000 PSI	-
56.	YF-PN16	1/2" (DN15) ~ 12" (DN300)	Flanged	Y-Type Strainers	PN16	-
57.	YF-PN40	1/2" (DN15) ~ 12" (DN300)	Flanged	Y-Type Strainers	PN40	-
58.	WA-001	1/2" (DN15) ~ 8" (DN200)	Flanged	Wafer Type Piston Check Valve	PN40/16	-
59.	WA-002B	1/4"(DN8) ~ 4" (DN100)	Butt Weld	2 Pieces Spring Check Valve	PN40	-
60.	WA-002S	1/4"(DN8) ~ 4" (DN100)	Socket Weld	2 Pieces Spring Check Valve	PN40	-
61.	WA-002T	1/4"(DN8) ~ 4" (DN100)	Threaded	2 Pieces Spring Check Valve	PN40	-
62.	YS-800	1/4"(DN8) ~ 3" (DN80)	Scr./SW	Y-Type Strainers	PN40/800PSI	-
63.	GT-200	1/4"(DN8) ~ 2" (DN50)	Threaded	Gate Valve	PN16/200PSI	-
64.	GB-200	1/4"(DN8) ~ 2" (DN50)	Threaded	Globe Valve	PN16/200PSI	-
65.	HPV-40	1/4"(DN8) ~ 2" (DN50)	Scr./SW/BW /Fla.	3 Pieces	Class 1500/3000PSI/ PN210	Full/ Reduced Bore
66.	HPV-41	1/4"(DN8) ~ 2" (DN50)	Scr./SW/BW /Fla.	3 Pieces	Class2500/600 0PSI/PN420	Full/ Reduced Bore
67.	SC-200	1/4"(DN8) ~ 3" (DN80)	Threaded	Swing Type Check Valve	PN16/200PSI	-
68.	YGB-800	1/4"(DN8) ~ 2" (DN50)	Threaded	Y Type Globe Valve	800PSI	-
69.	MD-28	1/2" (DN15)~6"(DN150)	Flanged	2 Pieces	Class 150/Class 300/PN10/PN1 6/PN25/PN40	Full Bore
70.	MD-82	1/2" (DN15)~12"(DN300)	Flanged	2 Pieces	Class 150/Class 300/PN10/PN1 6/PN25/PN40	Full Bore
71.	V-358B	1/4" (DN8) ~ 4" (DN100)	Butt Weld	3 Pieces	1000/800PSI/P N63/PN40	Full Bore
72.	V-358S	1/4" (DN8) ~ 4" (DN100)	Socket Weld	3 Pieces	1000/800PSI/P N63/PN40	Full Bore
73.	V-358T	1/4" (DN8) ~ 4" (DN100)	Threaded	3 Pieces	1000/800PSI/P N63/PN40	Full Bore
74.	K-338L/T	1/2" (DN15) ~ 2" (DN50)	Threaded	3 ways L/T port	1000PSI/PN63	Full Bore
75.	K-338TC	1/2" (DN15) ~ 2" (DN50)	T-Clamp	3 ways L/T port	1000PSI/PN63	Tube Bore
76.	K-314L/T	1/2" (DN15)~ 3" (DN80)	Scr./SW/BW	3 ways L/T port	1000PSI/PN63	Full Bore
77.	K-315L/T/ X	1/2" (DN15)~ 3" (DN80)	Scr./SW/BW	4 ways L/T/X port	1000PSI/PN63	Full Bore
78.	KF-315L/T /X	1/2" (DN15) ~ 6" (DN150)	Flanged	4 ways L/T/X port	C150/PN16	Full Bore